Vehicle log Book details:

Name of the work:- Engagement of Gang man and hiring of tractor Tipper for cleaning Roadside and maintanance of Road side drains & other civil work in ward No-15

Estimated cost:- Rs 1100000=00

Name of the Contractor:- Nagaraj Hosur

Job Code :- 015-17-000051

AS :- EE-DD-AS-30/17-18 dtd 01-08-17

TS:- EE-DD-TS-20/17-18 date 02/08/2017

ಸಹಾಯಕ ಇಂಜಿನಿಯರ್
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

		Labourers	KA-04-A1576	KA-52-M-1524
1)	18/12/2017	21	1	—
2)	19/12/2017	26	1	—
3)	20/12/2017	24	1	1
4)	21/12/2017	24	1	—
5	22/12/2017	26	1	—
6	23/12/2017	26	1	—
7	24/12/2017	23	1	1
8)	26/12/2017	24	1	—
9)	27/12/2017	26	1	—
10)	28/12/2017	26	1	—
11	29/12/2017	26	1	—
12	30/12/2017	26	1	—
13	31/12/2017	20	1	1
	Total	317 Nos	13	3

Overseer
(AE)

Page

Names of the Places for desilting drains & Road Cleaning

Kempegowda Removing & desilting at Kempegowda Nagar 1st main Road 1st, 2nd, 3rd, 4th 5th 6th 6thA 6thB Cross Road

— do —

— do —

— do —

Removing & desilting at 2nd & 3rd main Road & 6th & 7th Cross Road

— do —

— do —

Bhuvaneshwari Nagar 5th main 1st, 2nd, 3rd, 4th, 5th Cross Roads.

Overseer
(AE, W-15)

ಸಹಾಯಕ ಇಂಜಿನಿಯರ್ (ಎಇಇ)
ಮಹಾದೇವಪುರ ವಲಯ-ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು

4	4)01/2018	26	1	—	Ganesh Sawmill main road & Cross Road
5	5/01/2018	26	1	1	1st, 2nd, 3rd, 4th Cross Road
6	6/01/2018	25	1	—	— ce —
7)	8/01/2018	25	1	—	— ce —
8	9/01/2018	26	1	—	Nelamaddhwamma main Road & Cross Rods
9	10/01/2018	26	1	1	— ce —
10	11/01/2018	26	1	—	— ce —
11	12/01/2018	26	1	—	K.R. Road and other Cross Roads
12	13/01/2018	26	1	—	— ce —
13	15/01/2018	25	1	1	Dasarahalli 1st main road and Cross Road 1st, 2nd, 3rd 4th Cross Road
14	16/01/2018	26	1	—	— ce — — ce —
15	17/01/2018	26	1	—	— ce — — ce —
16	18/01/2018	26	1	—	M.T.S Colony 1st main & 2nd main, 1st Cross 2nd Cross Road
17	19/01/2018	26	1	—	— ce —
18	20/01/2018	23	1	—	— ce —
19	22/01/2018	25	1	—	— ce —
20	23/01/2018	26	1	—	New Masudi main Road & Cross Road
21	24/01/2018	26	1	1	— ce —
22	25/01/2018	26	1	—	— ce —
23	26/01/2018	26	1	—	Colonel Cordon main Road & Cross Road
24	27/01/2018	24	1	—	— ce —
25	29/01/2018	26	1	—	— ce —
26	30/01/2018	26	1	1	— ce —
27	31/01/2018	26	1	—	
	Total	689	27	5	

(AE, W-15)

(AE, DNo 15)

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಮಾದನಾಯಕನಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

SL NO	Date	No of Laboures	No, of Tractor KA-04-A 1576	No of JCB KA-52-M-1521
1	1/2/2018	24	1	—
2	2/2/2018	26	1	1
3	3/2/2018	26	1	—
4)	5/2/2018	25	1	—
5	6/2/2018	26	1	—
6	7/2/2018	26	1	—
7	8/2/2018	26	1	1
8	9/2/2018	26	1	—
9	10/2/2018	26	1	—
10	12/2/2018	26	1	—
11	13/2/2018	25	1	—
12	14/2/2018	26	1	—
13	15/2/2018	26	1	1
14	16/2/2018	26	1	—
15	17/2/2018	24	1	—
16	19/2/2018	26	1	—
17	20/2/2018	26	1	1
18	21/2/2018	26	1	—
19	22/2/2018	26	1	—
20	23/2/2018	26	1	—
21	24/2/2018	26	1	—
22	26/2/2018	26	1	—
23	27/2/2018	26	1	1
24	28/2/2018	26	1	—
	Total	620	24	5

(Assistent Engineer)

Date
Page

Name of the Places for Cleaning / Removing & Cleaning the Roads by drain

S. Ramesh Road 1st 2nd 3rd 4th 2nd main Road Cross 1st 2nd 3rd 4th
— Do —
— Do —
— Do —

Kalasthi Nagar main Road & Cross Roads 1st 2nd 3rd 4th 5th 6th Cross Roads
— Do —
— Do —
— Do —
— Do —

Madelas Colonel main Roads and Cross Roads 1st 2nd 3rd 4th 5th 6th and other Cross Road
— Do —
— Do —
— Do —

Prasanth Nagar 1st main Road & Cross Roads
— Do —

(Assistent Engineer)

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲನಾ ಅಭಿಯಂತರರು
ಮಹಾನಗರಪಾಲಿಕೆ ಉಪ-ವಿಭಾಗ
ದಾವಣಗೆರೆ, ಪಶ್ಚಿಮ
ದಾವಣಗೆರೆ

Scanned by CamScanner

ND		Labours	KA-04-A-1576	KA-52-M-1521
1	1/8/2018	24	1	—
2	2/8/2018	26	1	—
3	3/8/2018	26	1	—
4	5/8/2018	24	1	—
5	6/8/2018	26	1	—
6	7/8/2018	26	1	1
7	8/8/2018	26	1	—
8	9/8/2018	26	1	—
9	10/8/2018	25	1	—
10	12/8/2018	25	1	—
11	13/8/2018	26	1	—
12	14/8/2018	26	1	—
13	15/8/2018	26	1	—
14	16/8/2018	26	1	—
15	17/8/2018	24	1	—
16	18/8/2018	5	1	—
17	19/8/2018	26	1	—
18	20/8/2018	26	1	—
19	21/8/2018	26	1	—
20	22/8/2018	26	1	—
21	23/8/2018	26	1	—
22	24/8/2018	25	1	1
23	26/8/2018	26	1	—
24	27/8/2018	26	1	—
25	28/8/2018	26	1	—
26	29/8/2018	26	1	—
27	30/8/2018	26	1	—
28	31/8/2018	25	1	—
	Total	697	28	2

(Asstt Engineer)

... the places for desilting, cleaning of drains.

Compe Gardan main Road & Cross Roads 1st 2nd 3rd 4th 5th

— ditto —

— ditto —

Pampa Mahakavi Road & cross Road Siddanna house road

— ditto —

— ditto —

Nrupathung Road and other cross Roads

— ditto —

— ditto —

— ditto —

Suntah Tent house main road Cross Roads 2nd, 3rd, 4th 5th 6th

— ditto —

— ditto —

Egale Bakary main Roads & Cross Roads

2nd, 3rd 4th 4th A 5th 6th Cross Roads

— ditto —

— ditto —

— ditto —

— ditto —

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಕಾಡುಗೋಡಿ ವಿಭಾಗ
ಬಾಗಲೂರು, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

(Asstt Engineer)

Scanned by CamScanner

SL No	date	No of Labours	No of tractor KA-04-A-1576	No of JCB KA52-M1524
1	2/4/2018	23	—	—
2	3/4/2018	25	—	—
3	4/4/2018	26	1	—
4	5/4/2018	26	1	—
5	6/4/2018	26	—	—
6	7/4/2018	25	—	—
7	9/4/2018	26	—	1
8	10/4/2018	25	—	—
9	11/4/2018	26	—	—
10	12/4/2018	26	—	—
11	13/4/2018	26	1	—
12	14/4/2018	25	—	—
13	16/4/2018	24	1	—
14	17/4/2018	26	1	—
15	19/4/2018	26	—	—
16	20/4/2018	26	1	—
17	21/4/2018	26	—	1
18	23/4/2018	26	1	—
19	24/4/2018	26	1	—
20	25/4/2018	25	—	—
21	26/4/2018	26	1	—
22	27/4/2018	26	—	—
23	28/4/2018	26	1	—
24	30/4/2018	25	—	—
	Total	613	9 day	2

Name of the Places for desilting and Cleaning of drain,

Amoggh Hotel back side Cross Roads

— " —

— " —

Dharmasthala Hotel main Road & Cross Road 1st 2nd 3rd 4th 5th cross Road

— " —

— " —

— " —

— " —

Rock line cinemas back side cross Roads.

— " —

— " —

— " —

Shiva Temple main Road & Cross roads. 1st and 2nd 3rd / 4th Cross Roads

— " —

— " —

— " —

Amma ji Convetional hall back side Roads

(Asstt. Engineer)

(AE)

ಮುಖ್ಯ ಕಾರ್ಯನಿರ್ವಾಹಣಾಧಿಕಾರಿ
ಬೆಂಗಳೂರು ಗ್ರಾಮಾಂತರ
ಜಿಲ್ಲಾ ಪಂಚಾಯತ್, ದೊಡ್ಡಬಳ್ಳಾಪುರ
ಬೆಂಗಳೂರು

Scanned by CamScanner

SL NO	Date	No of Labours	No of Tractor KA-04-A-1576	No of JCB KA-52-M-1521
1	3/5/2018	24	1	—
2	3/5/2018	26	1	—
3	4/5/2018	26	1	—
4	5/5/2018	26	1	—
5	7/5/2018	24	1	—
6	8/5/2018	26	1	—
7	9/5/2018	25	1	—
8	10/5/2018	26	1	—
9	11/5/2018	25	1	—
10	12/5/2018	26	1	—
11	13/5/2018	4	—	—
12	14/5/2018	26	1	—
13	15/5/2018	26	1	—
14	16/5/2018	26	1	1
15	17/5/2018	26	1	—
16	18/5/2018	25	1	—
17	19/5/2018	26	1	—
18	21/5/2018	25	1	—
19	22/5/2018	26	1	—
20	23/5/2018	25	1	—
21	24/5/2018	25	1	1
22	25/5/2018	26	1	—
23	26/5/2018	26	1	—
24	28/5/2018	25	1	—
25	29/5/2018	25	1	—
26	30/5/2018	26	1	—
27	31/5/2018	26	1	—
	Total	664	26	2 day

Name of the Places for desilting and Cleaning of drain

Jain temple main Road & Cross Road
1st — 2nd, 3rd, 4th & 5th cross Roads
— ee —
— ee —
— ee —

Bhuvaneswari Nagar 1st main Road & Cross Roads
1st — 2nd, 3rd, 4th 5th 7th Cross Roads
— ee —
— ee —
— ee —

Dr, Ramachandra hospital Backside efde Cross Roads
— ee —
— ee —
— ee —

Prime line road Rright side Cross Road.
1st 2nd 3rd 4th 5th
— e —
— e —
— e —

Assistant Engineer

Assistant Engineer

Scanned by CamScanner